

9

10

11

G

11



6

detail Z SCALE 4:1

6



8



TRIMETRIC VIEW

Η

G

С

RO/

5

NOTES:

- 1. MAGNETS SHOULD BE PLACED IN THE BOTTOM OF THE MAGNET CARRIER POCKETS AND EPOXIED INTO PLACE WITH HYSOL 4212 EPOXY ADHESIVE.
- 2. THE POLE FACES OF THE MAGNET MUST BE ORIENTED AS SHOWN IN DETAIL VIEW "Z" AND RELATIVE TO KEYING FEATURE AS SHOWN ON DETAIL "Y". MAGNETS MUST BE 100% TESTED FOR MAGNET ORIENTATION.
- 3. EPOXY PERMITTED IN MAGNET POCKETS ONLY. ALL OTHER SURFACES MUST BE EPOXY FREE.
- 4. EPOXY MUST COMPLETELY COVER THE MAGNETS BUT REMAINS BELOW THE HOUSING SURFACE.
- 5. THE SYMBOL \bigcirc WITH INCLUDED NUMBER INDICATES THE SEQUENCE OF NOTING INSPECTION REPORTS.
- 6. PARTS SHALL BE CLEAN AND FREE OF CRACKS, FOREIGN MATTER, DISCOLORATION, CHIPS, WELD OR FLOW LINES AND WARPAGE UNLESS APPROVED BY ZF DESIGN ENGINEERING.
- 7. BOTH MAGNETS WITHIN THE MAGNET CARRIERS SHALL BE FROM THE SAME MATERIAL LOT TO REDUCE MAGNET TO MAGNET VARIATION.
- 8. RECOMMENDE FASTNER AND TORQUE: M4 CAP SCREW 2.82 Nm (25 LBS-IN)

		E									
	DWN: AF	CO	NFIDENTIAL AN	ID PROPRIETAR	Y:		9				2 P
	APVD: SM	ALL INFORMATION OR INVENTIONS CONTAINED IN THIS DOCUMENT OR DERIVED FROM THE INFORMATION THERE									
	CONFIDENTIAL AND PROPRIETARY, REVIEW OR POSSESSION OF THIS DOCUMENT INDICATES AGREEMENT				ZF Electronic Systems						
	THIRD ANGLE PROJECTION	ON THAT SUCH INFORMATION AND INVENTIONS WILL NOT BE DISCLOSED, REPRODUCED OR OTHERWISE USED IN ANY WAY WITHOUT EXPRESS WRITTEN PERMISSION FROM AN AUTHORIZED REPRESENTATIVE OF ZF ELECTRONIC SYSTEMS. DAME / DESCRIPTION MAGNET CARRIER								I.S.A.	
IEK										ER	,
34681 2020-02-06 TCH TB		TOL	ERANCE UNL	ESS SPECIF	IED	С	ITEM	NO.	AS50	0106	
NO. DATE PREP APVI		mm	± 0.30	± 0.100	\pm 1.0°	SCA	LE:	1:1	SH 1	OF	1
ς Ι	·		3			2				1	